Approved For Re	elease 2007/01/18 : CIA-RDP78T05929A002000030003-3
•	TOP SECRET
(c) NATIONAL I	PHOTOGRAPHIC INTERPRETATION CENTER
	Attachment to 21 August 1966 Page 1
REFERENCE:	RAIL ACTIVITY NORTH VIETNAM
1. <u>SIGNIFICANCE</u> :	FOUR IMPORTANT BRIDGES, TWO ON THE RAIL LINE EXTEND- ING FROM KEP TO PING-HSIANG, CHINA AND TWO ON THE
	RAIL LINE UNDER CONSTRUCTION FROM KEP TOWARD THAI
	NGUYEN, ARE OBSERVED. THREE OF THESE BRIDGES ARE
	PROBABLY SERVICEABLE.
2. LOCATION:	THE BRIDGES ARE LOCATED AS FOLLOWS:
	A. THE BRIDGE OVER THE KINH KEP (CANEL) AT
	2125N- 10616E IS 1.5 NM NW OF KEP ON THE KEP/
9	THAI NGUYEN RAIL LINE UNDER CONSTRUCTION.
	B. THE BRIDGE OVER THE SONG THUONG (RIVER)
	AT 2127N - 10614E IS 4.5 NM NW OF KEP ON THE
	KEP/THAI NGUYEN RAIL LINE UNDER CONSTRUCTION.
	C. THE CAO NUNG BRIDGE OVER THE SONG HOA
	(RIVER) AT 2133N - 10629E IS 1 NM SW OF CAO
	NUNG AND 15.5 NM NE OF KEP ON THE KEP/PING-
	HSIANG RAIL LINE.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

GROUP :
Excluded from automotic
downgrading and declassification

TOP SECRET

2

25)

25

	Approved For Release 2007/01/18 : CIA-RDP78T05929A002000030003-3	
	TOP SECRET	25)
	(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER	
	Attachment to 21 August 1966 Page 2	25)
	D. A BY-PASS BRIDGE IS APPROXIMATELY 200 YARDS NW OF THE CAO NUNG BRIDGE.	
3.	BACKGROUND: LOW ALTITUDE PHOTOGRAPHY OF REVEALED BOTH BRIDGES ON THE KEP/THAI NGUYEN RAIL LINE UNDER CONSTRUCTION TO BE WITHOUT SPANS AND THERE-	25)
	FORE UNSERVICEABLE. THIS PHOTOGRAPHY ALSO RE- VEALED BOTH THE CAO NUNG BRIDGE AND ITS BY-PASS	
1	BRIDGE TO BE UNSERVICEABLE.	
4.	MISSION READOUT: SPANS ARE IN PLACE ON THE BRIDGE OVER THE KINH KEP (CANAL) AND ON THE BRIDGE OVER THE SONG THUONG (RIVER). THE BRIDGES	
	ARE PROBABLY SERVICEABLE. SCALE PRECLUDES IDENTIFICATION OF THE RAILHEAD AND ROLLING STOCK. SPANS ARE OBSERVED IN PLACE ON THE BY-PASS BRIDGE AROUND THE DESTROYED CAO NUNG BRIDGE OVER THE SONG HOA (RIVER). THE BY-	
	PASS BRIDGE IS PROBABLY SERVICEABLE.	25)

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

TOP SECRET

25)



